



PI 500

Hand-held instrument for industry

The new PI 500 is an all-purpose hand-held measuring instrument for many applications in industry like e. g.:

- Flow measurement
- Pressure/vacuum measurement
- Temperature measurement
- Moisture/dew point measurement

The graphic indication of coloured measurement curves is inimitably.

Up to 100 million measured values can be stored with date and name of measuring site. The measured values can be transferred to the computer by means of a USB stick.


The data can be comfortably evaluated with the CS Soft Basic software. Measured data

and service reports can be issued easily and quickly. The following sensors can be connected to the freely configurable sensor input of PI 500:

- Pressure sensor (high and low pressure)
- Flow sensors, VA 500/520
- Temperature sensors Pt 100, Pt 1000 / 4...20 mA
- Dew point sensors FA 510
- Effective power meters
- Optional third-party sensors with the following signals: 0...1/10 V, 0/4...20 mA, Pt 100, Pt 1000, pulse, Modbus

Special features:

- Universal sensor input for lots of common sensor signals
- Internal rechargeable Li-Ion batteries (approx.12h continuous operation)
- 3.5" graphic display / easy operation via touch screen
- Integrated data logger for storage of the measured values
- USB interface for reading out via USB stick
- International: Up to 8 languages selectable



Measurement curves are indicated graphically and thus the user can see at a glance the behaviour of the dryer since the start of the measurement.



All physical parameters of moisture measurement are calculated automatically.



It is possible to store up to 100 million measured values. Each measurement can be stored with a comment, e.g. measuring site name. The time interval can be freely determined.



PI 500

Flexible data recording and transfer via USB cable or USB stick



The stored measured data can be easily transferred to the computer via a USB stick or via a USB cable.

The time periods are freely selectable or you just read out the whole memory.

The data can be evaluated by means of the software CS Soft Basic in table and in graphic form.


World debut screenshot key

Ideal for documentation of the measured values/measurement curves on site. Coloured measurement curves can be sent by e-mail or integrated into a service report.

By means of the screenshot key the „current screen“ can be stored as an image file and printed out at the computer or edited without any additional software.

Data evaluation in 5 languages by means of CS Soft Basic

Everything at a glance: Table, graph, statistics - at the touch of a button the user gets all necessary information.



Graphic evaluation

All measurement curves are indicated in terms of colour. All necessary functions such as zoom, selection/deselection of single measurement curves, freely selectable time periods, scaling of the axis, selection of colours and so on are integrated:

This view can be stored as a pdf file and sent by e-mail. Different data can be consolidated to a common file.

Time	2P-4-20 (00000)	2P-4-20 (00000)	2P-4-20 (00000)	2P-4-20 (00000)
01/01/2013 00:00:00	11.8000	11.8000	11.8000	11.8000
01/01/2013 00:00:05	11.8000	11.8000	11.8000	11.8000
01/01/2013 00:00:10	11.8000	11.8000	11.8000	11.8000
01/01/2013 00:00:15	11.8000	11.8000	11.8000	11.8000
01/01/2013 00:00:20	11.8000	11.8000	11.8000	11.8000

Table view

All measuring points are listed with exact time interval. The desired measuring channels with measuring site name can be selected via the diagram explorer.

Statistic Report	
Time span: 01/01/2013 00:00:00 - 01/01/2013 00:00:00	
2P-4-20	
Statistic	Value
Maximum	11.8000
Minimum	11.8000
Average	11.8000
Standard Deviation	0.0000

Statistics

All necessary statistic data are visible at a glance.

So the user can quickly see which minimum or maximum measured values occurred at which time and for how long.



PI 500

Hand-held instrument with large range of sensors




Description	Order No.
PI500 portable measuring instrument with integrated data logger, incl. power supply	0560 0511
Option for PI 500: "mathematics calculation function" for 4 freely selectable „virtual“ channels	Z500 5107
Option for PI 500: „Totalizer function for analogue signals“	Z500 5106
CS Soft Basic - data evaluation in graphic and table form - reading out of the measured data via USB	0554 7040
Transportation case	0554 6510

Technical data PI 500:

Colour screen:	3.5"-Touchpanel TFT transmissive, graphics, curves, statistics
Interfaces:	USB
Power supply for sensors:	Output voltage: 24 VDC \pm 10% Output current: 120 mA continuous operation
Current supply:	Internal rechargeable Li-Ion batteries charging time approx. 4 h PI 500 operation: > 4h depending on current consumption of external sensors
Power supply unit:	100 - 240 VAC/50 - 60 Hz, 12 VDC - 1A Safety class 2, only for application in dry rooms
Dimensions:	82 x 96 x 245 mm
Material:	Plastic PC/ABS
Weight:	450 g
Operating temperature:	-20...70°C measuring gas temperature 0...50°C ambient temperature
Storage temperature:	-20 to +70°C
EMC:	DIN EN 61326
Sensor inputs:	for connection of pressure sensors, temperature sensors, clamp-on ammeters, third party sensors with 4...20mA, 0-10 V, Pt 100, Pt 1000
Memory size:	4 GB - SD memory card standard






Input signals

Current signal	(0...20mA/4...20mA) internal or external power supply
Measuring range	0...20 mA
Resolution	0.0001 mA
Accuracy	\pm 0.03 mA \pm 0.05 %
Input resistance	50 Ω
Voltage signal	(0...1 V) Measuring range
Resolution	0...1 V
Accuracy	0.05 mV
Input resistance	\pm 0.2 mV \pm 0.05 %
Voltage signal	(0...10 V / 30 V) Measuring range
Resolution	0...10 V
Accuracy	0.5 mV
Input resistance	\pm 2 mV \pm 0.05 %
RTD Pt 100	Measuring range
Resolution	-200...850°C
Accuracy	0.1°C
	\pm 0.2°C (-100...400°C) \pm 0.3°C (further range)
RTD Pt 1000	Measuring range
Resolution	-200...850°C
Accuracy	0.1°C
	\pm 0.2°C (-100...400°C)
Pulse	min pulse length 500 μ s
Measuring range	frequency 0...1 kHz max. 30 VDC





Suitable sensors for PI 500

Flow sensors VA 500:		Order No.	
Flow sensor VA 500 Max. Version (185 m/s) sensor length 220 mm, incl. 5 m cable to mobile instruments		0695 1124	
Flow sensor VA 500 High-Speed Version (224 m/s), sensor length 220 mm, 5 m cable to mobile instruments		0695 1125	
Option for VA 500:			
sensor length 120 mm		ZSL 0120	
sensor length 160 mm		ZSL 0160	
sensor length 300 mm		ZSL 0300	
sensor length 400 mm		ZSL 0400	
Flow measuring range VA 520 for compressed air:(ISO 1217: 1000 mbar, 20°C)			
Flow meter VA 520, 0,8... 90 l/min, (R 1/4" DN 8)		0695 0520	
Flow meter VA 520, 0,2... 90 m³/h, (R 1/2" DN 15)		0695 0521	
Flow meter VA 520, 0,3... 170 m³/h, (R 3/4" DN 20)		0695 0522	
Flow meter VA 520, 0,5... 290 m³/h, (R 1" DN 25)		0695 0523	
Flow meter VA 520, 0,7... 530 m³/h, (R 1 1/4" DN 32)		0695 0526	
Flow meter VA 520, 1,0... 730 m³/h, (R 1 1/2" DN 40)		0695 0524	
Flow meter VA 520, 2,0... 1195 m³/h, (R 2" DN 50)		0695 0525	
Dew point sensors:			
FA 510 dew point sensor for mobile instruments, -80...+20°Ctd, incl. mobile measuring chamber, 5 m cable and perforated cap		0699 1510	
FA 510 dew point sensor for mobile instruments, -20...+50°Ctd, incl. mobile measuring chamber, 5 m cable and perforated cap		0699 1512	
Connection cable for VA/FA sensors:			
Connection cable for VA/FA series on mobile instruments, ODU / M12, 5m		0553 1503	
Extension cable for mobile instruments ODU/ODU, 10m		0553 0504	
Calibration certificate for flow / dew point sensors:			
5 point precision calibration with ISO certificate		3200 0001	
Precision calibration at -40 °Ctd incl. ISO certificate		0699 3396	
Pressure sensors:	± 1 % accuracy of full scale	± 0,5 % accuracy of full scale	
Standard pressure sensor CS 16 from 0...16 bar	0694 1886	0694 3555	
Standard pressure sensor CS 40 from 0...40 bar	0694 0356	0694 3930	
Standard pressure sensor CS 1.6 from 0...1.6 bar abs.		0694 3550	
Standard pressure sensor CS 10 from 0...10 bar	0694 3556	0694 3554	
Standard pressure sensor CS 100 from 0...100 bar		0694 3557	
Standard pressure sensor CS 250 from 0...250 bar		0694 3558	
Standard pressure sensor CS 400 from 0...400 bar		0694 3559	
Precision pressure sensor CS -1...+15 bar, ±0.5 % accuracy of full scale	0694 3553		
Precision differential pressure sensor CS 400, 0...400 mbar differential pressure, 0.075% accuracy of full scale, static pressure max. 40 bar	0694 3560		
Calibration of pressure sensor 5 points between 0 and 10/16 bar	3200 0004		
Temperature sensors:			
Bendable temperature probe Pt 100 Class B, length 300 mm Ø 3 mm, -70...+500°C, 2 m probe connection cable glass fibre/stainless steel with ODU plug 8 pole for mobile instruments	0604 0106		
Screw-in temperature probe Pt 100 Class A, length: 300 mm with measuring transducer 4 to 20 mA = -50 to +500 °C (2-wire technology) (Please order additional the connection cable 0553 0501)	0693 0002		
Temperature probe cable Pt 100 Class A, length: 300 mm Ø 6 mm with 5 m connection cable with open ends (Please order additional the ODU plug Z604 0104)	0604 0102		
Temperature probe cable Pt 100 Class A, length: 150 mm Ø 6 mm with 5 m connection cable with open ends (Please order additional the ODU plug Z604 0104)	0604 0100		
Mini temperature probe cable Pt 100 Class A, length 25 mm, Ø 4 mm 50°C to +180°C, 5 m probe connection cable with open ends (Please order additional the ODU plug Z604 0104)	0604 0105		
Compression fitting 6mm, G1/2", VA clamp ring	0554 6004		
Temperature calibration certificate 2 measuring points	0520 0180		



Suitable sensors for PI 500

Connection cables for pressure sensors / temperature sensors:	Order No.
Connection cable for pressure, temperature or external sensors on mobile instruments, ODU / open ends, 5 m	0553 0501
Connection cable for pressure, temperature or external sensors on mobile instruments, ODU / open ends, 10 m	0553 0502
Extension cable for mobile instruments, ODU / ODU, 10 m	0553 0504
Mounted Odu plug for connection on mobile instruments	Z604 0104
Clamp-on ammeters:	
Clamp-on ammeter 0...400 A TRMS incl. 5 m connection cable	0554 0511
Clamp-on ammeter 0...1000 A TRMS incl. 5 m connection cable	0554 0519
Calibration certificate for clamp-on ammeter	0554 3333
CS PM 600 Current/effective power meter up to 100 A	0554 5341
CS PM 600 Current/effective power meter up to 600 A	0554 5342
Mobile current/effective power meter with 3 external current transducers for big machines and plants External current transformers for clamping on cables (100 or 600 A) External magnetic measuring tips for measuring the voltage Measures kW, kWh, cos phi, kVar, kVA Data transfer to PI 500 via Modbus Incl. connection cable for mobile current/effective power meter to mobile instruments, 5 m	
Current transformer 100A/1A consisting of 3 transformers for mobile instruments	Z554 0001
Current transformer 600A/1A consisting of 3 transformers for mobile instruments	Z554 0002
Current transformer 1000A/1A consisting of 3 transformers for mobile instruments	Z554 0003
Optional third-party sensors connectable:	
e.g. heat meters, current meters, gas meters, water meters and so on. To the freely assignable sensor input all sensors of CS Instruments can be connected as well as optional third-party sensors and counters with the following signal outputs: 4-20 mA I 0-1 V / 0-10 V / 0-30 V I Pt100 (2- or 3-wire), Pt 1000 (2- or 3-wire), KTY I pulse outputs (e.g. of gas counters) I Frequency output I Modbus protocol	



Application: Portable flow measurement in production in front of machines and plants





Set for dryer monitoring



°Ctd

bar

°C

1	PI 500 portable measuring instrument with integrated data logger, incl. power supply	0560 0511
2	FA 510 dew point sensor for mobile instruments, -80...+20°Ctd incl. mobile measuring chamber, 5 m cable	0699 1510
3	Standard Pressure sensor CS 16 from 0...16 bar, ± 1 % accuracy of full scale	0694 1886
4	Connection cable for pressure, temperature or external sensors to portable instruments, ODU / open ends, 5 m	0553 0501
5	Bendable temperature probe Pt100 Class B, length 300 mm, ø 3 mm, -70...+500°C, 2 m probe connection cable glass fibre/stainless steel with ODU plug 8 pole for portable instruments	0604 0106
6	CS Soft Basic - data evaluation in graphic and table form - reading out of the measured data via USB	0554 7040
7	Transportation case	0554 6510

Set for portable flow measurement



m³/h

1	PI 500 portable measuring instrument with integrated data logger, incl. power supply	0560 0511
2	Flow meter VA 520, 0,3... 170 m ³ /h, (R3/4" DN 20)	0695 0522
3	Connection cable for VA/FA Series on mobile instruments, ODU / M12, 5 m	0553 1503
4	CS Soft Basic - data evaluation in graphic and table form - reading out of the measured data via USB	0554 7040
5	Transportation case	0554 6510



Chart recorder

Standard set compressed air



m³/h


°Ctd

bar

°C

1	PI 500 portable measuring instrument with integrated data logger, incl. power supply	0560 0511
2	Flow sensor VA 500 Max. Version (185 m/s) sensor length 220 mm, incl. 5 m cable to portable instruments	0695 1124
3	FA 510 dew point sensor for mobile instruments, -80...+20°Ctd incl. mobile measuring chamber, 5 m cable	0699 1510
4	Standard Pressure sensor CS 16 from 0...16 bar, ± 1 % accuracy of full scale	0694 1886
5	Connection cable for pressure, temperature or external sensors to portable instruments, ODU / open ends, 5 m	0553 0501
6	Bendable temperature probe Pt100 Class B, length 300 mm, ø 3 mm, -70...+500°C, 2 m probe connection cable glass fibre/stainless steel with ODU plug 8 pole for portable instruments	0604 0106
7	CS Soft Basic - data evaluation in graphic and table form - reading out of the measured data via USB	0554 7040
8	Transportation case	0554 6510

Professional set compressed air



m³/h

°Ctd

bar

°C

A

1	PI 500 portable measuring instrument with integrated data logger, incl. power supply	0560 0511
2	Flow sensor VA 500 Max. Version (185 m/s) sensor length 220 mm, incl. 5 m cable to portable instruments	0695 1124
3	FA 510 dew point sensor for mobile instruments, -80...+20°Ctd incl. mobile measuring chamber, 5 m cable	0699 1510
4	Standard Pressure sensor CS 16 from 0...16 bar, ± 1 % accuracy of full scale	0694 1886
5	Connection cable for pressure, temperature or external sensors to portable instruments, ODU / open ends, 5 m	0553 0501
6	Bendable temperature probe Pt100 Class B, length 300 mm, ø 3 mm, -70...+500°C, 2 m probe connection cable glass fibre/stainless steel with ODU plug 8 pole for portable instruments	0604 0106
7	Clamp-on ammeter 0...400 A RMS 10-30 VDC for portable instruments, 3 m cable, ODU 8 pol.	0554 0511
8	CS Soft Basic - data evaluation in graphic and table form - reading out of the measured data via USB	0554 7040
9	Transportation case	0554 6510